

Summit Auto Detailing

Service Enhancement Additional Information

Service Enhancements:

- 1. Clay bar:** Removes physical embedded contaminants from painted and glass surface, which washing alone cannot remove. Yields smoother painted surfaces and improved wax and sealant adhesion.
- 2. Clay bar and iron decontamination:** Removes embedded contaminants and staining effects of brake dust and other types of iron particle fallout. Clay barring must be performed in addition to iron decontamination to yield quality results. Iron decontamination results are most noticeable on lighter colored vehicles, but may also noticeably benefit heavily contaminated darker colored vehicles.
- 3. Ceramic paint sealant:** Application of a ceramic sealant to the painted surfaces, providing ceramic infused protection to the vehicles surface, lasting 4-6 months under real world conditions. Provides superior chemical resistance, gloss, durability, smoothness, and water beading, which regular waxes alone cannot achieve.

Summit Auto Detailing

Service Enhancement Additional Information

- 4. Tar removal:** Removes road tar from vehicle's exterior surfaces, commonly found on vehicle trim and in wheel wells after driving through construction zones.
- 5. Rain-X glass treatment:** Applies Rain-X glass treatment to all exterior vehicle glass. Provides excellent water repellence and drastically improves visibility in wet conditions, while also allowing for reducing wiper usage.
- 6. Engine bay detailing:** Thorough washing of engine bay surfaces and trim, and application of protectant to engine parts and accessories.
- 7. Fabric protection package:** Full interior shampooing and stain removal, followed by an application of a long-life fabric protectant, guarding against staining and dye transfer.
- 8. Smoke odor removal:** Removes smoke odor from interior surface. All interior surfaces are extensively scrubbed and are constantly checked for odor emission, in addition to ozone treatment, typically achieving above 80% of odor removal immediately, with remaining odor quickly fading with time. Interior HVAC filters are not changed.